CREO SYLLABUS

1: INTRODUCTION TO CREO PARAMETRIC

Introduction to Creo Parametric
Feature-Based Nature
Bidirectional Associative Property
Parametric Nature
System Requirements
Getting Started with Creo Parametric
Important Terms and Definitions
File Menu Options Managing Files Menu Manager Model Tree
Understanding the Functions of the Mouse Buttons
Ribbon Toolbars Navigator
Creo Parametric Browser Appearance Gallery Rendering in Creo Parametric
Colour Scheme Used in this Book

2: CREATING SKETCHES IN THE SKETCH MODE-I

The Sketch Mode
Working with the Sketch Mode
Invoking the Sketch Mode
The Sketcher Environment
Working with a Sketch in the Sketch Mode
Drawing a Sketch Using tools available in the Sketch Tab
Placing a Point Drawing a Line Drawing a Centreline
Drawing a Geometry Centreline
Drawing a Rectangle Drawing a Circle Drawing an Ellipse Drawing an Arc
Dimensioning the Sketch
Converting a Weak Dimension into a Strong Dimension
Dimensioning a Sketch Using the Normal Tool
Dimensioning the Basic Sketched Entities
Linear Dimensioning of a Line

Angular Dimensioning of an Arc
Diameter Dimensioning Radial Dimensioning Dimensioning Revolved Sections
Working with Constraints Types of Constraints Disabling Constraints
Modifying the Dimensions of a Sketch
Using the Modify Button
Modifying a Dimension by Double-Clicking on it
Modifying Dimensions Dynamically
Resolve Sketch Dialog Box Deleting the Sketched Entities Trimming the Sketched Entities Mirroring the Sketched Entities
Inserting Standard/User-Defined Sketches
Drawing Display Options

3: CREATING SKETCHES IN THE SKETCH MODE-II

Dimensioning the Sketch
Dimensioning a Sketch Using the Baseline Tool
Replacing the Dimensions of a Sketch Using the Replace Tool
Creating Fillets
Creating Circular Fillets
Creating Elliptical Fillets
Creating a Reference Coordinate System
Working with Splines Creating a Spline Dimensioning of Splines Modifying a Spline
Writing Text in the Sketcher Environment
Rotating and Resizing Entities
Importing 2D Drawings in the Sketch Mode

4: CREATING BASE FEATURES

Creating Base Features Invoking the Part Mode The Default Datum Planes Creating a Protrusion
Extruding a Sketch
Revolving a Sketch
Understanding the Orientation of Datum Planes
Parent-Child Relationship
Implicit Relationship
Explicit Relationship
Nesting of Sketches

5: DATUMS
Datums
Default Datum Planes Need for Datums in Modeling Selection Method in Creo Parametric Datum Options
Datum Planes
Creating Datum Planes
Datum Planes Created On-The-Fly
Datum Axes
Datum Points
Creating Cuts
Removing Material by Using the Extrude Tool
Removing Material by Using the Revolve Tool

6: OPTIONS AIDING CONSTRUCTION OF PARTS-I

Options Aiding Construction of Parts
Creating Holes
The Hole Dashboard
Important Points to Remember While Creating a Hole
Creating Rounds
Creating Basic Rounds
Creating a Variable Radius Round
Points to Remember While Creating Rounds
Creating Chamfers Corner Chamfer Edge Chamfer
Understanding Ribs
Creating Trajectory Ribs
Creating Profile Ribs
Editing Features of a Model
Editing Definition or Redefining Features
Reordering Features Rerouting Features Suppressing Features Deleting Features Modifying Features

7: OPTIONS AIDING CONSTRUCTION OF PARTS-II

Introduction
Creating Feature Patterns Uses of patterns Creating Patterns Deleting a Pattern
Copying Features New Refs Same Refs Mirror
Move
Select
Mirroring a Geometry
Creating a Section of a Solid Model
Work Region Method

8: ADVANCED MODELING TOOLS-I

Other Protrusion Options
Sweep Features
Creating Sweep Protrusions
Aligning a Sketched Trajectory to an Existing Geometry
Creating a Thin Sweep Protrusion
Creating a Sweep Cut
Blend Features Parallel Blend Rotational Blend General Blend
Using Blend Vertex
Shell Feature
Creating a Constant Thickness Shell
Creating a Variable Thickness Shell 8
Datum Curves
Creating a Datum Curve by Using the Curve Button
Creating a Datum Curve by Sketching
Creating a Curve by Using the Intersect Option Creating a Curve by Using the Project Option
Creating a Curve by Using the Wrap Option
Creating Draft Features

9: ADVANCED MODELING TOOLS-II
Advanced Feature Creation Tools
Variable Section Sweep Using the Sweep Option

Swept Blend
Helical Sweep
Blend Section to Surfaces
Blend Between Surfaces

10: ADVANCED MODELING TOOLS-III

Advanced Modeling Tools
Toroidal Bend Spinal Bend Warp
Transform Tool Warp Tool Spine Tool Stretch Tool Bend Tool Twist Tool Sculpt Tool

11: ASSEMBLY MODELING

Assembly Modeling
Important Terms Related to the Assembly Mode
Top-down Approach Bottom-up Approach Placement Constraints Package
Creating Top-down Assemblies
Creating Components in the Assembly Mode
Creating Bottom-up Assemblies
Inserting Components in an Assembly
Assembling Components
Displaying Components in a Separate Window
Displaying Components in the Same Window
3D Dragger
Applying Constraints Status Area Placement Tab
Move Tab
Packaging Components
Creating Simplified Representations Redefining the Components of an Assembly Reordering
Components Suppressing/Resuming Components Replacing
Assembling Repeated Copies of a Component
Modifying the Components of an Assembly
Modifying Dimensions of a Feature of a Component
Redefining a Feature of a Component
Creating the Exploded State References Tab Offset Tab Explode Line Tab
The Bill of Materials Global Interference Pairs Clearance

12: GENERATING, EDITING, AND MODIFYING THE DRAWING VIEWS

The Drawing Mode
Generating Drawing Views Generating the General View Generating the Projection View Generating
the Detailed View Generating the Auxiliary View Generating the Revolved Section View Generating
the Copy and Align View Generating the 3D Cross-Section View
Editing the Drawing Views Moving the Drawing View Erasing the Drawing View Deleting the
Drawing View
Adding New Parts or Assemblies to the Current Drawing
Modifying the Drawing Views Changing the View Type Changing the View Scale Reorienting the
Views Modifying the Cross-sections Modifying Boundaries of Views
Adding or Removing the Cross-section Arrows
Modifying the Perspective Views
Modifying Other Parameters
Editing the Cross-section Hatching

13: DIMENSIONING THE DRAWING VIEWS

Dimensioning the Drawing Views
Show Model Annotations Dialog Box
Adding Notes to the Drawing
Adding Tolerances in the Drawing Views
Dimensional Tolerances
Geometric Tolerances
Editing the Geometric Tolerances
Adding Balloons to the Assembly Views
Adding Reference Datums to the Drawing Views
Modifying and Editing Dimensions
Modifying the Dimensions Using the Dimension Properties Dialog Box
Modifying the Drawing Items Using the Shortcut Menu
Cleaning Up the Dimensions

14: OTHER DRAWING OPTIONS

 Sketching in the Drawing Mode Modifying the Sketched Entities User-Defined Drawing Formats
Retrieving the User-Defined Formats in the Drawings
Adding and Removing Sheets in the Drawing Creating Tables in the Drawing Mode Generating the
BOM and Balloons in Drawings

15: SURFACE MODELING

Surface Modeling
Creating Surfaces in Creo Parametric Creating an Extruded Surface Creating a Revolved Surface
Creating a Sweep Surface Creating a Blended Surface Creating a Swept Blend Surface Creating a
Helical Sweep Surface
Creating a Surface by Blending the Boundaries
Creating a Variable Section Sweep Surface Using the Sweep Tool
Creating Surfaces the Using the Style Environment of Creo Parametric
Style Dashboard
Surface Editing Tools Mirroring the Surfaces Merging the Surfaces Trimming the Surfaces Creating
the Fill Surfaces Creating the Intersect Curves Creating the Offset Surfaces Adding Thickness to a
Surface
Converting a Surface into a Solid
Creating a Round at the Vertex of a Surface
Freestyle modelling environment
Freestyle Dashboard

WITH INDUSTRIAL LIVE PROJECTS